

# Work Order ID 73112

Thursday, August 25, 2011 4:10:16 PM



Page 1

Item ID: D206-581-015

Accept



Setup Start



Revision ID:

Stop



Item Name: Step Handle Installation

Start Date: 8/26/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 9/9/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: CL Date: 11/08/26

Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

Run Start



QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_

Date: \_\_\_\_\_

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D206-581	C

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPPD206-581-015

CHG001

*Handwritten:* S u l o o b / 31 11-08-30

110

0.00



Pick Kit

Packaging

Memo

0.00

Packaging

*Handwritten:* sl

*Handwritten:* sp 11-08-30

120

0.00



QC4- 100% Inspect kits for completeness

QC

Memo

0.00

Quality Control

*Handwritten:* S u l o o b / 31



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

**Work Order ID 73112**

Thursday, August 25, 2011 4:10:16 PM

Page 2

Item ID: D206-581-015

Accept

Revision ID:

Item Name: Step Handle Installation

Start Date: 8/26/2011 Start Qty: 1.00

Required Date: 9/9/2011 Req'd Qty: 1.00



Reference:


Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Run Start

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130 	Packaging	0.00							
Packaging	<b>Memo</b>	0.00							
Packaging	Identify and pack for shipping as per PPP D206-581-015 Location: <u>                    </u> PPP Rev: <u>                    </u>								
140 	QC21- Final Inspection - Work Order Release	0.00							
QC	<b>Memo</b>	0.00							
Quality Control									

11/8/31 

MF  
11-08-31

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Thursday, August 25, 2011 4:10:13 PM

Page 1

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the team.

3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources needed to complete each task.

4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress regularly to ensure that the project is on track.

5. The final step is to evaluate the results of the project. This involves comparing the actual outcomes against the objectives and goals to determine the effectiveness of the project.

[illegible]

**Required Qty: 1.00**

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

**Loc Code**

**Loc Code**

**Loc Code**

Loc Code

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

# Picklist Print

Page 2

Thursday, August 25, 2011 4:10:13 PM

Work Order ID: 73112



Parent Item: D206-581-015



Parent Item Name: Step Handle Installation

Start Date: 8/26/2011

Required Date: 9/9/2011

Start Qty: 1.00

Required Qty: 1.00

NAS1149D0463J

Purchased

No

110

Each

4,160.000



Washer



5/2 11-08-30

Location

Loc Qty

Loc Code

ST298

4160

116025

16

116805

0

117291

1

117460

2

117591

108

118179

67

118384

2966

118612

1000

2x

Thursday, August 25, 2011 4:10:13 PM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries



## 5.0 PART LIST

### 5.1 D407-581-111/-011 AND D206-581-113/-013/-014/-015/-017 KITS

Qty -111	Qty -113	Qty -011	Qty -013	Qty -014	Qty -015	Qty -017	Part Number	Description
X							D407-581-111	PRE-FLIGHT KIT (407)
	X						D206-581-113	PRE-FLIGHT KIT (206A/B/L/L1/L3/L4)
2		X					D407-581-011	PRE-FLIGHT STEP KIT, LH/RH (407)
	1		X				D206-581-013	PRE-FLIGHT STEP KIT, LH (206A/B/L/L1/L3/L4)
	1			X			D206-581-014	PRE-FLIGHT STEP KIT, RH (206A/B/L/L1/L3/L4)
4	4				X		D206-581-015	STEP HANDLE KIT
						X	D206-581-017	RETENTION STRAP KIT
						2	D3031-3	LOOP
		1	1	1			D4101-041	PRE-FLIGHT STEP ASSEMBLY
			1				D4102-1	SHIM (206 LH)
				1			D4102-2	SHIM (206 RH)
		1					D4102-3	SHIM (407)
					1		D4103-1	STEP HANDLE
						1	D4104-041	DOUBLER ASSEMBLY
						1	D4105-1	STRAP
						2	80-004-2D8	INSERT
					2		80-005-3-8	INSERT
		6	6	6			80-005-3-16	INSERT
						8	CR3243-4-1	RIVET
						2	MS21042L3	NUT
						2	MS24694-S47	SCREW
						2	MS24694-S50	SCREW
						2	MS24694-S52	SCREW
					2		MS27039-4-11	SCREW
		6	6	6			MS27039-4-14	SCREW
						2	NAS1149D0332J	WASHER (or AN960JD10L)
		6	6	6	2		NAS1149D0416J	WASHER (or AN960JD416L)
					2		NAS1149D0463J	WASHER (or AN960JD416)